



## (A Govt. of India Undertaking) REGIONAL OFFICE, HYDERABAD

No.TQC/HYD/Pur/Wooden Crates/TS/2018-19

Dt.04-09-2018

## CORRIGENDUM

The following diagram has been depicted at page No.43 of tender bearing No. TQC/HYD/Pur/Wooden Crates/TS/2018-19, dt.28-08-2018:

ſ	•	•		•	•
				100	
				,	
ŀ	•	•		•	•
					13
			,	-	•
	•	•			

In supersession of the above diagram, the revised diagram shall be as under:

••		00	•
••	•		•
	Salar Mills		
• • • • • • • • • • • • • • • • • • •	•	•	
	•	•	

Note: There is no change in the specifications. Nails shall be 28 Nos. in all, as prescribed at point No.7, page 42 of tender document.

REGIONAL MANAGER